

# Cycle PH+ R+ 1

	J2	J3	J4	J5	J6	J7
2, 50	X	X	X	X	X	X
2, 50	X	X	X	X	X	X
2, 50	X	X	X	X	X	X
2, 50	X	X	X	X	X	X
2, 50	X	X	X	X	X	X
2, 50	X	X	X	X	X	X
2, 50	X	X	X	X	X	X
2, 50	X	X	X	X	X	X
Angle	X		X	X		X
1, 20	X	X	X	X	X	X
1, 20	X	X	X	X	X	X
1, 20	X	X	X	X	X	X
1, 20	X	X	X	X	X	X
1, 20	X	X	X	X	X	X
0, 60	X	X	X	X	X	X
0, 60	X		X	X	X	X
0, 60	X		X	X	X	X
0, 60	X			X	X	X
0, 28	X	X	X	X	X	X
0, 28	X	X	X	X	X	X
0, 28	X	X	X	X	X	X
0, 28	X	X	X	X	X	X
0, 15	X	X	X	X		X
0, 15	X	X	X	X		X
0, 15	X	X	X	X		X
RCM	X		X	X	X	
RCM	X		X	X	X	
RCM	X		X	X	X	

J0 PH+ 2eme

J0 PH+ 2eme

} J0 PH+ 2eme